

PARTS LIST

Part	Description	Qty	Part	Description	Qty
1	Screw M5x20	1	17	External hexagon bolt M8 × 100	1
2	Chuck 13mm	1	18	Bracket	1
3	Output shaft	1	19	Auxiliary handle	1
4	Semicircular key 10x3	1	20	Depth guage	1
5	Dust ring	1	21	Plastic cover	1
6	Bearing 6001	1	22	Rubber column 4x9	1
7	Circlip 12 for shaft	1	23	Screw ST4x16	10
8	Big gear	1	24	Impact block	1
9	Taper spring	1	25	Impact iron sheet	1
10	Flat pad 8.1x12x0.5	1	26	Motor housing	1
11	688 bearing	1	27	Switch	1
12	Impact bracket ass.	1	28	Carbon brush	2
13	608 bearing	2	29	Capacitance 0.33μF	1
14	Armature	1	30	Inductance	1
15	Wool block	1	31	Brush box	2
16	Stator	1	32	Cable sheath	1
	Stator insulation end plate	1	33	power cable	1
	Insulation end plate of stator outgoing line	1			

ASSEMBLY DIAGRAM

