

PART LIST

No.	Description
1	Stents Component
2	Shaft lock clips
3	Saw frame clips
4	Saw frame press plate
5	body assembly
6	Machine screw
7	Motor+PCB+Switch Assembly
8	bottom rubble pad
9	front rubble pad
10	Back Cover
11	Shell
12	Quick lock button
13	Tapping Screw
14	Damping connecting block
15	Damping connecting block
16	Handspike
17	spring
18	Battery Pack(not included)
19	T rubble pad
20	Nameplate
21	Quick lock button

ASSEMBLY DIAGRAM

