

PARTS LIST

| No. | Description           | No. | Description         |
|-----|-----------------------|-----|---------------------|
| 1   | Inverted screw        | 13  | Speed Button        |
| 2   | chuck                 | 14  | Speed Button Spring |
| 3   | Torque sleeve         | 15  | Shell               |
| 4   | Torque sleeve ferrule | 16  | Switch Assembly     |
| 5   | Tapping Screw         | 17  | PCB                 |
| 6   | Gearbox               | 18  | Stents              |
| 7   | Motor Gear            | 19  | Buffle              |
| 8   | Machine screw         | 20  | Battery Pack        |
| 9   | Motor                 | 21  | Transparent Cover   |
| 10  | Back shell            | 22  | Belt Clip           |
| 11  | Handspike             | 23  | Machine screw       |
| 12  | Varlable Steel        | 24  | Magnet Ring         |

### ASSEMBLY DIAGRAM

