

PARTS LIST

Part	Description	Qty
1	Drill chuck	1
2	Gear Box	1
3	Spindle	1
4	6001 Bearing	1
5	Wheel Gear	1
6	606 Bearing	1
7	Middle Cover	1
8	608 Bearing	1
9	Rotor	1
10	Brush Holder	2
11	Carbon Brush	2
12	Stator	1
13	608 Bearing	1
14	Switch	1
15	Switch knob	1
16	Housing	1
17	Cable Protector	1
18	Cable and Plug	1

ASSEMBLY DIAGRAM

